

# Paint spillage saving by installing collecting tray

**Location:** Galco Steel (BD) Ltd., Bangladesh

**Process:** Metal sheet manufacturing

## Before

- The company used to lose around 1.6% paint due to spillage
- Around 950 L paint per day was used which included wastage in the color coating unit
- No collecting tray was installed on the floor to collect the spilled paint



## After

- The company has installed new collecting trays below all color coating machines
- This has enabled the company to save around 4,600 litre paint annually
- Housekeeping in the color coating unit has also improved



## Costs/benefits

**Cost:** Nil (*As company manufactures metal sheet by themselves*)

**Annual savings:** 4,600 litre paint

**Contact:** Dr. M Balakrishnan, [malinib@teri.res.in](mailto:malinib@teri.res.in)  
Mr. Rajat Batra, [rajat.batra@stenum-asia.org](mailto:rajat.batra@stenum-asia.org)  
Mr. Khandoker Anwar Kamal, [project@dhakachamber.com](mailto:project@dhakachamber.com)  
Ms. Nizhum Islam Nishi, [nishi.fahim@live.com](mailto:nishi.fahim@live.com)

**Disclaimer:** This document has been produced with the financial assistance of the European Union. The contents of this document are the sole responsibility of TERI and can under no circumstances be regarded as reflecting the position of the European Union.